GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/EH/WZ/

Dated: 6/10/22

Sh. Rakesh Mehta, House No.23 41, Ground floor, Sector-3, Rohini, Delhi-110085.

Sub: Issue of FSC in r/o M/s J. W. Solitaire Restaurant, A unit of Guru Ji Associates, Unit No. 114 to 121, Plot No.15, N. N. Mall, Manglam Plaza, Sector-3, Rohini, Delhi-110085. Sir.

Kindly reference to online application No. 2022081016039 dated 12.08.2022, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 12.09.2022 in presence of Sh. Rakesh Mehta to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

- 1. The width of door is 2.0m & 1.2m against the required width of two doors of 1.50 mtr.
- 2. Natural ventilation not provided.
- 3. Smoke Detector system in restaurant not provided.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

 $\frac{\text{http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms}$

Yours faithfully

(Atul-Garg) DIRECTOR Ph. 011-23414000

Copy to:

1. The Manger, M/s J. W. Solitaire Restaurant, A unit of Guru Ji Associates, Unit No. 114 to 121, Plot No.15, N. N. Mall, Manglam Plaza, Sector-3, Rohini, Delhi-110085