

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/GH/2022/SZ/ 920 To Dated: 31.7.10../2022

The Addl. Commissioner of Police, Lic/Branch, 1st Floor, P.S Defence Colony New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Alpina Hotel & Suites Located at E- 506, Greater Kailash-II, New Delhi 110048

Sir,

This has reference with MHA Portal ID 2022053111761 dated 10-06-2022 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 15.10.2022 in the presence of Mr. Sumeet of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus Three Upper Floors. The shortcomings observed are as below:

- 1. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016
- 2. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER