



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/EH/NDZ/2022/ 654

Dated: 9.10.2022

To

The Deputy Commissioner (Licensing)
1st Floor, Police Station Defence Colony,
New Delhi.

Subject:- Online Application ID No.- **2022093018454** in r/o **M/s Asia 21 Restaurant running at 1st floor** situated at **F-21, Main Road Vikas Marg, Preet Vihar, Delhi –110092.**

Sir,

This has a reference to online application ID No.- **2022093018454** dated **30.09.2022** received on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 14.10.2022 in the presence of **Dr. K.K. Juneja (Owner)** and observed that building comprised of Ground + 03 upper floors but restaurant is running at First floor only and following shortcomings were observed during inspection :

1. Width of one staircase is reduced than required width due to encroachment.
2. Fire pump capacity of 450 LPM provided but not functional.
3. 20,000 liter. Overhead water tank found removed.

In addition to above the application needs correction in respect of width of staircase, width of door and width of corridor. Accordingly, the applicant may be directed to furnish correct information and compliance of above shortcomings for further necessary action for issuance of Fire Safety Certificate.

Hence the online application is rejected.

Yours faithfully,


(S.K. Dua)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Manager,
M/s Asia 21 Restaurant running at 1st floor,
F-21, Main Road Vikas Marg, Preet Vihar, Delhi –110092.