

C-34

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110001**

No: F.6/DFS/MS/School/2022/SZ/698

Dated: 18/11/22

To,

The Principal,  
Mata Bhatee Devi Public School,  
Plot No.1, Main Goyla Dairy Road, A-161,  
Todarmal Colony, Shyam Vihar, Deenpur, Najafgarh, New Delhi-110043

**Sub: -** Regarding issuance of Fire Safety Certificate in r/o Mata Bhatee Devi Public School, Plot No.1, Main Goyla Dairy Road, A-161, Todarmal Colony, Shyam Vihar, Deenpur, Najafgarh, New Delhi-110043.

Sir,

This has reference to your letter No. 2022-2023/83 Dated 28/09/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 02/11/2022 to verify the fire safety arrangements in accordance with the Rules. At the time of inspection Sh Sunny Jakhar (V.Principal) was present and it was observed that the school building is comprised of Two Blocks Old block (Ground plus one upper floor) & New block having (Small basement , ground plus three upper floors) and have following shortcomings.

1. First Aid Hose Reel provided but not functional.
2. Fire pump having 450 LPM provided but not functional
3. Exit Signage's provided but not sufficient.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Sunil Chawdhary)

**Dy. Chief Fire Officer**  
Delhi Fire Service

Copy to:-

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.

**(With a request to take further action as school does not have fire NOC)**