

C6

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/WZ/2022/ 713

Dated: 23/11/2022

To,

The Principal,
MCD Pratibha Bal Vidyalaya,
Budh Vihar-II,
Delhi-110086.

Sub: Issue of FSC in r/o MCD Pratibha Bal Vidyalaya, Budh Vihar-II, Delhi-86.

Sir,

This is in reference to your letter No. nil dated 23.07.2022 received through outdoor diary no. 3977 dated 01.07.2022 on the subject cited above. The premise was inspected by the concern nominated authority of this department on **03.11.2022**, in presence of **Sh. Nira Bhardwaj (In-Charge)** to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

1. Accessible gate width of 3.80 mtr against the required width of gate 4.5mtr.
2. First Aid hose reel not provided.
3. Over Head water captive tank of 10,000 ltrs not provided.
4. Terrace Fire pump with capacity 450 LPM not provided.
5. The required exit signage are not provided.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Forms

Yours faithfully



(Atul Garg)
DIRECTOR
Ph; 011-23414000

etc
my