

e-27

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2021/NDZ/ 688

Dated: 28/12/2021

To,

The Authorized signatory,
Adhunik Education Society,
D-Block, Anand Vihar,
Delhi-110092

Subject:- Request for renewal of Fire NOC for PRUDENCE JUNIOR (A.U.O-ADHUNIK EDUCATION SOCIETY).

Sir,

With reference to your email ID anandvihar@prudenceonline. dated 21/10/2021 on the subject cited above, it is informed that officer concerned of this department visited the school building in the presence of Sh. Dhananjay, Manager on dated 20/12/2021 and observed that the shortcomings issued vide letter No. F.6/DFS/MS/School/2021/NDZ/748 dated 31/03/2021 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully,


27/12/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

qc Ar.

Copy to:-

1. The Dy. Director (Education),
D-Block Anand Vihar,
Delhi-110092

C-27

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTER : DELHI FIRE SERVICE : NEW DELHI – 110001**

No. F6/DFS/MS/School/2021/२५६

Dated 31/03/2021

To,

The Commissioner, EDMC
419, FIE Patparganj Ind. Area,
Delhi-110092

Sub: Regarding Fire Safety Certificate in r/o Adhunic Education Society at D-Block, Anand Vihar, Delhi-110092.


Sir,

This has reference to online reference ID no.- 10085022 dated 17/03/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by Divisional Officer (ED) & Asstt. Divisional Officer (LN) of this department on 25/03/2021 in the presence of Mr. Subhash Chand Jain and the following shortcomings were observed:-

1. Fire Check Door shall be required in the basement.
2. Corridor converted in activity room.
3. Doors opening on demolish portion.
4. Ventilation not provided in the basement.
5. Pump is not on auto mode and badly leakage

Hence, Fire Safety Certificate suspended.

Yours faithfully


31/3/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. Authorized signatory,
Adhunic Education Society,
D-Block, Anand Vihar,
Delhi-110092.
2. The Dy. Director (Education)
D-Block, Anand Vihar,
Delhi-110092