

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F.6/DFS/MS/2022/ 539

Dated:- 09/03/2022

To,

Sh. Jaivir Singh ,  
Receiver /Administrator  
DCM Building,  
16, Barakhamba Road , New Delhi.

Sub:- Regarding renewal of FSC in r/o DCM building , 16 Barakhamba Road, New Delhi.

Sir,

This has reference to your letter No.16/2022/R/A dated 31.01.2022 & dated 11.02.2022 on the subject cited above. In this regard, it is to inform that the site was re-inspected by the officers concerned of this department on 07/03/2022 in the presence of Sh. Arunesh Trivedi (Estate Manager) and the following shortcomings are still existing : -

1. Fire check doors at 6<sup>th</sup> ( vacant floor ),7<sup>th</sup> floor ( Panacia Bio tech ) & 9<sup>th</sup> floor ( PNB ) are still not provided.
2. The fire water hydrant line ruptured at 4<sup>th</sup> floor, during checking of operability/function ability of Pumps & firefighting arrangements.

In view of above, you are requested to submit the compliance of above shortcomings at the earliest, however, the time limit as prescribed in DFS Rules -2010 has already exhausted. Further, the occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully



(Atul Garg)  
DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect, NDMC, Palika Kendra, New Delhi.