

C-89

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/171

Dated:-25.02/2022

To,

The Manager,
Guruvas Guest House,
1049 & 982 , Main Bazar, Kumahar Wali gali,
Mantola , Pahar Ganj, New Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/S Guruvas Guest House, at 1049 & 982 , Main Bazar Kumahar Wali gali, Mantola, Pahar Ganj, New Delhi. ID No. 2022020701781 dated 07.02.2022.


Sir,

This has reference to on line ID No. 2022020701781 dated 07.02.2022 & email <hotelguruvasinndelhi@gmail.com> dated 08.02.2022 on the subject cited above. In this regard, it is to inform you that the site was visited by the officer concerned of this department on dated 15.02.22 in presence of Mr. Pappu and found that the shortcomings issued vide letter no.F6/DFS/MS/GH/NDZ/2021/799 dated 17.11.2021(copy enclosed) are still not complied in toto. .

In view of above, the renewal of FSC can not be issued at this stage. Therefore you are requested to abide by our previous letter for inspection for further consideration in the matter.

Yours faithfully,

Encl; as above


24/2/22

(Dr. S.K.Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to :-

1. The Addl. Commissioner of Police (Lic.) First floor, PS Defense Colony, New Delhi.

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

C-75

No.F6/DFS/MS/GH/NDZ/2021/ 799

Dated:-17/11/2021

To

The Manager,
M/S Guruvas Guest House,
Plot No 1049 & 982,
Main Bazar, Kumhar Wali Gali, Mantola,
Pahar Ganj, New Delhi.

Sub: Regarding grant of FSC in r/o M/S Guruvas Guest House Plot No 1049 & 982, Main Bazar, Kumhar Wali Gali, Mantola, Pahar Ganj, New Delhi. ID NO. 2021093023017 dated 01.10.21

Sir,

This has a reference to online ID No. 2021093023017 dated 01.10.21 on the subject cited above, it is to inform you that the site was visited by the officer concerned of this department on dated 08.11.21 and following shortcomings were observed: -

1. Smoke management at upper floors is not provided as per Gazette Notification dated 27.05.2019.
2. CO type detectors are not provided as per Gazette Notification dated 27.05.2019.
3. PA System found non functional,
4. Hose Reel found nonfictional.
5. Section elevation plan of the building is not submitted/uploaded.
6. Undertaking regarding not to use any floor above second floor is required to be submit.

Further, the name of guest house mentioned in the building plans is Guruvas Inn whereas in online application form it is mentioned Guruvas. The same may also be clarified.

Hence, Fire Safety Certificate (FSC) cannot be issued at this stage. Therefore, you are requested to submit the compliance of the shortcoming for further consideration in the matter.

Yours faithfully


18/11/21

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service



Copy to :-

The Addl. Commissioner of Police (Lic.), Licensing Unit, Defence Colony Police Station, New Delhi.