

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F.6/DFS/MS/NDZ/2022 | 569

Dated:-.../03/2022

To

The Executive Engineer / ESD,  
Council of Scientist & Institute Research,  
Building no. 02 Rafi Marg, New Delhi.

**Sub:- Regarding renewal of FSC in r/o of CSIR building no. 02 Rafi Marg, New Delhi.**

Sir,

This has reference to your letter No. nil dated 04.02.2022 on the subject cited above. In this regard, it is to inform that the site was inspected by the officers concerned of this department on 02.03.2022 in the presence of Sh. Arun Misra, EE & Sh. Prasanna, AE(E) and the following shortcomings were observed:-

1. Corridor found encroached by storing of almirah and others items.
2. Hose reel & hydrant are not provided in basement and terrace floor of main block. Nozzles from some hose reels also found missing.
3. Detectors are not provided at second floor and some found nonfunctional at a few places & canteen.
4. Temporary offices found constructed at terrace level , accordingly approval of terrace floor ( fifth floor) from building sanctioning authority is required to be submitted.

In view of above shortcomings, request for renewal of fire NOC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

  
(Atul Garg)  
DIRECTOR  
Delhi Fire Service

**Copy to :**

The Chief Architect,  
New Delhi Municipal Council, Palika Kendra, New Delhi.