

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2022/ 137

Dated: 25 /03/2022

To,

The Principal, Montfort School, Ashok Vihar, New Delhi-110052.

Sub: - Regarding Renewal of Fire Safety Certificate in r/o Montfort School Located at <u> Ashok Vihar, Phase- 1, Delhi – 110052.</u>

Sir,

Please refer to your Email dated 11/02/2022 on the subject cited above. In this connection, it is to inform you that the said building/premises was inspected by the officer concerned of this department on 09/03/2022 in presence of Sh. Brother. Thampy Alex to see the functioning of fire safety equipments provided in the building.

During inspection, it has been observed that the above said school is running at total four blocks 02 blocks G + 3 upper floors, 01 Block G + 2 upper floors all three blocks are interconnected & one new block is G + 3 upper floors. Fire safety arrangements Such as Fire Extinguishers, First -Aid Hose reels, Over head water storage tank, etc. are provided. However the following Shortcomings were observed.

- 1. Terrace fire pump of 450 lpm & 180 lpm is provided but not functional.
- 2. Exit Sinages are found removed.

In view of above Shortcomings the application for Renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The educational authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

(Dharampal Bhardwaj) Dy. Chief Fire Officer

> West Zone 02/3/02

Copy to: -

1. The Director, Directorate of Education, old secretariat, Delhi.