

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/Institutional/2023/SZ/ 120

Dated: 20/01/2023

To,

The President,
Shri Maa Education Society (Regd.),
Institute of Innovation in Technology & Management,
D-27 & 28, Institutional Area, Janakpuri, New Delhi-110058

Sub: Regarding renewal of Fire Safety Certificate in respect of Shri Maa Education Society (Regd.), Institute of Innovation in Technology & Management, D-27 & 28, Institutional Area, Janakpuri, New Delhi-110058

Sir,

This has reference to your email letter dated 14/03/2022, on the subject cited above. In this connection this is to inform you that the above mentioned building was jointly inspected by the officers concerned of this department on 23/03/2022. At the time of inspection Mr. Rajeev Gaur, (Professor) was also present at site. During the course of inspection it was observed that the building is comprised of Basement, Ground plus five upper floors was issued FSC by this department vide letter No. F.6/DFS/MS/2026/SZ/606 dated 19/04/2016. The following shortcomings was observed as :

1. 06 mts. Width of internal road found only one side of building which required all around the building.
2. Terrace Fire pump of 900 lpm capacity found removed.
3. MOEFA provided but not functional.
4. PA system provided but not functional.
5. Automatic sprinkler system not provided in some areas of basement.
6. Few fire extinguishers found vacant in building.
7. The additional area of basement is now under use which was sealed earlier.

In view of above shortcomings, Fire Safety Certificate' can not be granted at this stage. You are advised to rectify the above shortcomings under intimation to this department for taking further necessary action. The use of premises is at your risk & cost.

Yours Faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

24-