

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/D/S/MS/Business/ND//2022/ 3109

Dated: 13/12/2022

To,

The Commissioner,  
Municipal Corporation of Delhi,  
Dr. SPM, Civic Centre, New Delhi - 02.

**Sub:** Regarding renewal of Fire Safety Certificate in respect of **Akarshan Bhawan** located at **4754-57/23, Ansari Road, Darya Ganj, Delhi.**

Sir,

This has reference to outdoor diary no. 7963 dated on 14.11.2022 on the subject cited above. It is to inform you that the building/ premises was inspected by the officer concerned of this department on dated 04.12.2022 in the presence Sh. Ashwani Chandhary (Owner S-12) During inspection, following shortcomings were observed:

1. Fire extinguishers are due for refilling.
2. First aid hose reel found non functional.
3. Alternate power source for control panel not provided.
4. MOEFA not provided.
5. Public address system found not functional.
6. Automatic sprinkler system in basement found not functional.
7. Pumping arrangements at terrace level found removed.
8. Exit signages are not adequately provided.
9. Over head water storage tank requirement of 50,000 ltrs found removed.
10. Lift signages are not provided.
11. Standby power supply not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

The applicant is requested to rectify the shortcomings at the earliest for further action.

Yours faithfully

  
(Atul Garg)  
Director  
Delhi Fire Service  
Tel:-011-23414000  
o/c  
SK  
MN

Copy to:-

The Manager, Akarshan Bhawan at 4754-57/23, Ansari Road, Darya Ganj, Delhi.