

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F.6/DFS/MS/2023/ 231

Dated: 06/02/2023

To

Sh. Vivek Kumar,  
Estate Manager,  
Indra Prakash Building,  
21, Barakhamba Road, New Delhi.

**Sub:- Regarding renewal of FSC in r/o Indra Prakash Building, 21- Barakhamba Road, New Delhi-110001.**


Sir,

This has a reference to your letter no. nil dated 02.12.2022 on the subject cited above, it is to inform you that the site was inspected by the officers concerned of this department on 24/01/2023 in the presence of Sh. Ram Milan and the following shortcomings were observed:-

1. Fire check doors required for compartmentation, found removed at some floors.
2. Smoke management system provided in basement found nonfunctional and also not covering entire area to escape out smoke need to extended to left out area.
3. Detectors are not provided in some offices and common corridor also.
4. Exit signages found inadequate in basement.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

  
6/2/2023  
(Virendra Singh)  
Chief Fire Officer  
Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

✓ 