

C/74

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/SZ/2023/ 64

Dated: 06/02/2023

To,

The Principal ,
Bal Bhavan International School,
Sector – 12, Dwarka,
New Delhi - 110075.

Subject: Issuance of Fire Safety Certificate in r/o Bal Bhavan International School, Sector – 12, Dwarka, New Delhi – 110075.

Sir,

Please refer to your letter No. BBIS/DW/MCD/2023/429, dated 14/01/2023 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officer concerned from this department on 24/01/2023 in the presence of Mr. C M Vashist (Manager).

During the course of inspection following shortcomings are observed.

1. School activity is notice in basement.
2. Fire check door & lift lobby found not provided.
3. Pressurization system found not provided for lift.
4. Hose reel hoses found damage at some places.
5. MOEFA found nonfunctional.
6. At terrace 450 + 180 lpm pump provided against the required of 1620 lpm.
7. Overhead tank of 15000 ltrs capacity found provided against required 25,000 ltr capacity.
8. Exit Signage not provided at appropriate places.

You are requested to comply the above mentioned shortcomings under intimation to this department.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,


(Atul Garg)
Director
Delhi Fire Service

Copy to:-

1. Directorate of Education Old Secretariat Delhi – 110054.