

C-4

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2022/WZ/ 95

Dated: 27/02/2023

To,

The Principal,
Shree Ji World School,
Kh. No. 23/24 Jain Colony,
Prehladpur Banagar, Delhi-110039.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Shree Ji World School, Kh. No. 23/24 Jain Colony, Gurudwara Lane, Prehladpur Banagar, Delhi-110039.

Sir,

This has reference to your email id dated 07.02.2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 14.02.2023 to see the compliance of the requisite fire safety measures. Sh. Divij Babbar was present at the time of inspection. During the course of inspection it was observed that the school building comprised of Basement+ Ground+ One upper floor. Your request of issuance of FSC is rejected as the following shortcomings were observed:-

1. Fire check door not provided in basement.
2. Clear door width found 1.10 m against the required width of 1.20 m.
3. Smoke management system not provided in basement.
4. Terrace level pump and electric panel found installed inside the staircase which have to be removed from there.
5. Over Head Water tank of 10,000 ltrs. capacity provided against the required capacity of 15,000 ltrs.
6. Exit Signage not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully,

(Atul Garg)

Director
Delhi Fire Service

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.