

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI – 110001**

NO. F6/DFS/MS/SZ/2023/ 127

DATED: 20/03/2022

To,

Smt. Deepa Joshi (Principal) <universaldocs109@gmail.com>  
Universal Public School,  
G-109, Mandir Marg, Mahavir Enclave,  
Palam Dabri Road, New Delhi.

**Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Universal Public School Located at G-109, Mandir Marg, Mahavir Enclave, Palam Dabri Road, New Delhi.**

Sir,

Please refer to your Email Dated 23-02-2022 on the subject cited above. In this connection it is to inform to you that the above said building has been inspected by the officer concerned of this department on 10/03/2022 in presence of Smt. Deepa Joshi (Principal) and observed that one new block has been constructed.

During the course of inspection followings shortcomings was observed:-

1. Two stairs of 1.5m width are not provided for newly constructed block/ floor.
2. The passage/ corridor lead to stairs must have clear width of 1.5M.
3. The fire fighting system must be extended to newly constructed block/floor.
4. The capacity of terrace fire water tank must not be less than 10000 ltrs.

In view of the above shortcomings, fire safety certificate cannot be issued. You are advised to rectify the said shortcomings under intimation to this department for taking further necessary action.

Yours faithfully,

  
(Atul Garg)  
(Director)  
Delhi Fire Service