

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2023/WZ/ 215

Dated: 02/05/2023

To,
The Principal,
Silver Oak Public School,
G-111, Som Bazar Road, Ph-II,
Vijay Vihar, Rohini, Rohini,
Delhi-110085.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Silver Oak Public School located at G-111, Som Bazar Road, Ph-II, Vijay Vihar, Rohini, Rohini, Delhi-110085.

Sir,

This has reference to your letter no. SOPS/03/2023 received via outdoor diary no. 12085 dated 09.03.2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 20.04.2023 to see the compliance of the requisite fire safety measures. Sh. Vinod Kumar (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of Ground and Two Upper Floors. Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. Width of staircase found 1.50 m & 1.40 m against the required width of 1.50 m each.
2. There is only 01 continuous staircase to terrace against requirement of 02
3. First Aid Hose Reel not provided.
4. Terrace level pump of 450 lpm capacity not provided.
5. An overhead tank of 10,000 ltrs capacity not provided.
6. Exit signage's not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Atul Garg)
Director

Ph. 011-23414000

Atul Garg

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.