

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2023/SZ/254  
To

Dated 06/06/2023

The Addl. Commissioner of Police,  
Lic/Branch, 1<sup>st</sup> Floor, P S Defence Colony  
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Hotel Atithi located at F-5, East of Kailash New Delhi-110037

Sir,

This has reference with MHA Portal ID 2023051909287 dated 19-05-2023, 2023040405282 dated 17/05/2023 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 27/05/2023 in the presence of Mr Ajay Sharma. During the inspection, it was observed that the Guest House is running 2<sup>nd</sup> & 3<sup>rd</sup> floor in the building comprised of Basement ground plus three upper floors. The shortcomings observed are as below:

1. Fire check doors not provided as per clause 7.31 of UBBL 2016.
2. Smoke management system not provided in the upper floor as per clause 7.31 of UBBL 2016.
3. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
4. Fire fighting pumps are not functional
5. Terrace level tank capacity 2000 ltrs provided against the required capacity of 5,000 ltrs.
6. Exit signage found removed at some places.
7. Temporary structure at Terrace not acceptable as per clause 7.31 in UBBL 2016.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. M/s Hotel Atithi located at F-5, East of Kailash New Delhi-110037