

C-23

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2023/ 1280

Dated: 20/06/2023

To,

SHO/South Rohini,

Rohini Distt.

Delhi-110085.

Sub: Issue of FSC in r/o Staff Quarters at Police Station, Rohini, Sector-3, New Delhi-85.

Sir,

Kindly reference to online e-mail dated 20.03.2023, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 06.06.2023, in presence of **Sh. Arjun Singh (SHO)** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Lift lobby pressurization found removed.
2. FCD of staircases found damaged.
3. Fire pumps are not in working condition.
4. MOEFA not working.
5. Hose cabinets found locked and no key found accessible in premises.
6. No communication device found in lift.
7. Lift shaft pressurization found removed.
8. Fire /man switch found damaged.
9. Wet riser / hose reel are found non functional.
10. Water hydrant line found rusted & required to be painted.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/htt
p://www.delhi.gov.in/wps/wcm/connect/doiit_fire/FIRE/Home/Forms

Yours faithfully


(Arul Garg)
DIRECTOR
Ph; 011-23414000

SLC
CA