

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/GH/2023/SZ/ 334

Dated: 12/07/2023

To

The Addl. Commissioner of Police (Lic/Unit), 1st Floor, P.S. Defence Colony, New Delhi–110049.

Sub: Regarding issuance of FSC in r/o M/s Bed and Chai Guest house located at R-55, 2nd Floor, Greater Kailash-1, New Delhi 110048

Sir,

This is in reference with MHA Portal ID 2023062011200 dated 23/06/2023 on the subject cited above. In this connection, it is to inform you that the premise have been inspected by officer concerned of this department on 06/07/2023 in the presence of Mr. Satish (Manager) and observed that the Guest House is running in Second & Third Floor only. During the course of inspection, the following shortcoming observed were noticed:-

- 1. There is one staircase having width of 1m against the required two Staircase having width of 1.5 mtr each.
- 2. Smoke management system not provided as per clause 7.31 of UBBL -2016.
- 3. First Aid Hose reel not provided.
- 4. Carbon Monoxide detector not provided as per clause 7.31 of UBBL-2016.
- 5. MOEFA Not provided.
- 6. Internal hydrant not provided
- 7. Terrace level fire fighting pump capacity 450 LPM not provided.
- 8. Overhead tank capacity 10,000 ltrs not provided.
- 9. Exit signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

DIRECTOR

DELHI FIRE SERVICE