

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/Institutional/2023/SZ/ 1514

Dated: 20/07/2023

To,

The President,  
Shri Maa Education Society (Regd.),  
Institute of Innovation in Technology & Management,  
D-27 & 28, Institutional Area, Janakpuri, New Delhi-110058

Sub: Regarding renewal of Fire Safety Certificate in respect of Shri Maa Education Society (Regd.), Institute of Innovation in Technology & Management, D-27 & 28, Institutional Area, Janakpuri, New Delhi-110058

Sir,

This has reference to your letter No. IITM/DFS/-FSC-2023/3476 dated 12/05/2023 on the subject cited above. In this connection this is to inform you that the above mentioned building was inspected by the officers concerned of this department on 01/06/2023. At the time of inspection Mr. Rajeev Gaur, (Professor) was also present at site. During the course of inspection it was observed that the building is comprised of Basement, ground plus five upper floors and have following shortcomings:-

1. 06 meter width of internal road found only one side of building which required all around the building.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk & liability of the owner/occupier. The Licensing Authority/Statutory Authority may be take suitable necessary action as deemed fit.

Yours Faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

*[Handwritten signature]*