

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/NDZ/2023/ 1538

Dated: 24 07 .2023

To

Sh. Santanu Pratap Singh Parihar, Dy. Manager (Tech. & HR),

Scope Minar, Plot No. 2A-2B, Laxmi Nagar, Delhi-92

Subject:- Regarding issuance of Fire Safety Certificate in r/o Scope Minar at Plot No. 2A-2B, Laxmi Nagar, Delhi-92.

Sir.

This has reference to your email dated 04/07/2023 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 10/07/2023 in the presence of Mr. Nurul Ain (Sr. Manager) and the following shortcomings were observed :-

- 1. Fire check doors not provided in Core-I.
- 2. Electrical shafts not sealed at some floors.
- 3. P.A system is of poor audio quality needs to improve.
- Exit/lift signage not provided at some floors.

In view of above shortcoming, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfull

DEMHI FIRE SERVICE

el des