

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI- 110001**

F.6/DFS/MS/GH/2023/SZ/367 No.

Dated: 36./.07./2023

To

The Addl. Commissioner of Police, Lic/Branch, 1st Floor, P.S Defence Colony New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s HOTEL KIAN at L-316, Mahipalpur Extn. NH-8, New Delhi 110037

Sir.

This has reference with MHA Portal ID 2023071112349 dated 13-07-2023 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 21.07.2023 in the presence of Mr. Balram (Manager) of the Guest House. During the inspection, it was observed that the Guest House is running Basement, Ground plus Four Upper Floors. The shortcomings observed are as below:

1. Fire check doors not provided in the building as per clause 7.31 of UBBL 2016.

2. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016

3. First aid hose reel provided but not functional.

4. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

5. MOEFA provided but not functional.

6. Automatic sprinkler system not functional in the basement.

7. Fire Fighting pumping arrangements provided but not functional.

8. Overhead tank capacity 10,000 ltrs found removed.

9. The occupancy at 4th floor not acceptable as per clause 7.31 of UBBL 2016.

The management of building has made additional/alteration of 4th floor has also been addled. Hence, there is a material changed in the building Vis a Vis earlier approval of this department.

The management is here by advised, either you may restore the earlier composition of building profile or otherwise submits application for sanction of building plans on common application form (CAF) with present floor wise occupancy, on the scales as mentioned in UBBL 2016, for further consideration in the matter.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority

may take suitable necessary action as deemed fit.

LHI FIRE SERVICE

Copy to:-

1. M/s HOTEL KIAN at L-316, Mahipalpur Extension, NH-8, New Delhi 110037