



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2023/SZ/ 1894

Dated: 28 / 08 /2023

To,

Mr. P. Venkateswara Rao (Unit Head Finance), Asian Development Bank, At 4 San Martin Marg, Chanakyapuri, New Delhi -110021.

Sub: - Inspection report of Renewal in r/o: M/s Asian Development Bank at 4 San Martin Marg, Chanakyapuri, New Delhi -110021.

Sir,

Please refer to your letter received through Outdoor dairy application no. 4361 dated 01/08/2023 on the subject cited above, in this connection, it is to inform you that the said premises was re-inspected by the team of officers concerned of this department on 18/08/2023 in the presence of Mr. P. Venkateswara Rao (Unit Head Finance) from fire safety point of view. The building comprised of Basement + Ground plus Four upper floors only.

Following shortcomings were observed during the time of inspection:-

1. System was not integrated.

Electrical Shaft found not shield at 3rd floor.

3. Exhaust fan installed in basement shall be shifted.

4. Sprinkler found covered under false ceiling in kitchen & lounge needs to be extended.

In view of above, the application for issuance fire safety certificate is rejected .the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing authority/statutory authority may take suitable necessary action as deemed fit.

TUIJEARG)

Yours faith

Delhi Fire Service

Copy to:-

 Chef Architect, New Delhi Municipal Council, Department of Architecture & Environs, Palika Kendra, New Delhi.