

cl

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.
To

F.6/DFS/MS/School/2023/SZ/ 403

Dated: 14.09.2023

The Principal,
Swami Vivekanand Bal Bharti School,
B-1/329-330, Madangir, New Delhi 110062

Sub.- Regarding issuance of Fire Safety Certificate in r/o Swami Vivekanand Bal Bharti School, at B-1/329-330, Madangir, New Delhi 110062

Sir,

This has reference to your letter received through outdoor diary no 3912 dated 17/07/2023 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 01/09/2023 in the presence of Mrs. Richa Gupta (Manger). During the inspection it was observed that school is running at ground plus three upper floors. Accordingly fire safety arrangement were tested / checked and found following observation.

1. There is one staircase having width of 0.75 mtr against the required two staircase having width of 1.50 mtr each.
2. The exit doors width is 1 mtr against the required width of 1.20 mtr each.
3. First aid hose reels not provided.
4. Terrace level fire fighting pumps capacity 450 LPM not provided.
5. Overhead tank of 10,000 ltrs not provided

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054