

032

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/School/2023/422
To,

Dated: 20/09/2023

The Principal,
Sanskar public School,
Pocket-1, Sector-24,
Rohini, Delhi-110085

Sub: Issue of FSC in r/o Sanskar public School, Pocket-1, Sector-24, Rohini, Delhi-110085.

Sir,

Kindly reference to online e-mail dated 30.08.2023, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 06.09.2023, in presence of **Mr. Mukesh Solanki** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Fire check door not provided in basement.
2. Smoke Management System in basement not provided and basement found used at the time of inspection.
3. Automatic sprinkler system in basement not provided.
4. Hose reel hose not extended on ground floors & basement.
5. Terrace Fire pump with capacity 450 & one jockey pump capacity of 180 LPM provided but not functional.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:
<http://www.delhi.gov.in/wps/wcm/connect/doi fire/FIRE/Home/Fire+Safety+Acts+and+Rules/htp://www.delhi.gov.in/wps/wcm/connect/doi fire/FIRE/Home/Forms>

Yours faithfully


(Atul Garg)
DIRECTOR
Ph; 011-23414000

ae
mf