

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2023/SZ/ **503**  
To

Dated: **29.09**..2023

The Addl. Commissioner of Police,  
Lic/Branch, 1<sup>st</sup> Floor, P.S Defence Colony  
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s HOTEL NORATAN PALACE at A-27, Road No 1,  
Mahipalpur Extn. New Delhi-110037

Sir,  
This has reference with MHA Portal ID 2023080814203 dated 06/09/2023 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 25.09.2023 in the presence of Mr. Kamal Singh of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus three Upper Floors. The shortcomings observed are as below:

1. Fire check door not provided as per clause 7.31 of UBBL 2016
2. Smoke management system not provided in upper floors as per clause 7.31 of UBBL 2016.
3. First aid hose reel provided but found not functional.
4. Carbon monoxide detector not provided as per clause 7.31 of UBBL 2016.
5. Terrace level fire fighting pumps provided but found nonfunctional.
6. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE