



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/Bldg./SZ/2023/ 3027

Dated: 05/10/2023

To

Sh. Atul Naithani (DGM-Northern Region),
Indian Oil Corporation Limited,
Indian Oil Bhawan, 1, Sri Aurobindo Marg,
Yusuf Sarai, New Delhi-110016

**Sub: Regarding renewal of Fire Safety Certificate in r/o Indian oil Corporation Limited,
Indian Oil Bhawan, 1, Sri Aurobindo Marg, Yusuf Sarai, New Delhi-110016**

Sir,

Please refer to your letter No. IOCL/NRO/ES/Fire NOC/Renewal/2023 dated 11/08/2023, received through outdoor diary No. 4860 dated 11/08/2023 on the subject cited above. In this connection, it is to inform you that said premises have been inspected by the team of officers of this department on 19/09/2023 in the presence of Mr. Aayush Bansal (Manager-ES) and the shortcomings observed are as below: -

1. The Ventilation system found provided but non-functional in basement.
2. Automatic fire detection and alarming system found removed in some chambers.
3. Automatic Sprinkler System found removed in some chambers.
4. Fire pump was not on auto mode.

In view of above shortcomings, the application for renewal of fire safety certificate is rejected. The occupancy of the building in the absence of requisite fire protection system/fire safety certificate shall be at the risk and liable of the management.

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director (Comm. & Inst.), DDA, Vikas Sadan, INA, Delhi.