

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2023/EH/ 593

Dated 30 / 0 /2023.

The Joint Commissioner of Police/ Lic, 1<sup>st</sup> Floor, Licensing Unit, Police Station Defence Colony, New Delhi.

Sub: - Regarding issuance of fire safety certificate in r/o M/s Flos Music Bar (A Unit of La Lagos Sante Hospitality Pvt. Ltd) located at Plot No. G-1, 2<sup>nd</sup> & 3<sup>rd</sup> floor, Model Town-III, Delhi-110009.

Sir,

This has reference to online MHA Portal I.D. No. 2023101817475 Dated: 19.10.2023 on the subject cited above. In this connection this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 26.10.2023 in the presence of Sh. Naveen Kumar to verify the fire safety arrangements as stipulated in NBC Part 4 and as well installed in the building. During the course of inspection it has been observed that the building/ premise is comprised of basement, stilt, upper ground & 03 upper floors but (Restaurant proposed at second floor & third floors only). Your request for FSC is rejected under Rule 35 (3) due to following shortcomings.

- 1 Fire check door not provided in basement & kitchen area.
- 2 Smoke ventilation system is not provided at upper floors.

3 Fire Extinguisher not provided.

- 4 Hose reel hose provided but not functional.
- 5 Automatic fire detection and alarming system provided but not functional.
- 6 MOEFA system provided but not functional.
- 7 Internal hydrants provided but not functional.
- 8 Ground level electrical driven fire pump capacity of 2280lpm., diesel engine pump 2280lpm & jockey pump 180lpm provided but not functional.
- 9 Terrace level firefighting pump capacity of 450lpm provided but not functional.
- 10 Under ground fire water tank capacity of 1 lakh liter under construction and overhead fire water tank 10,000ltr provided empty.
- 11 Exit signage and floor signage not provided in the building.
- 12 Standby power supply not provided.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of restaurant is at your own risk & responsibility.

Yours faithfully

Ph: 011-23414000

22/10