प्री⁵ आज़ादी का अमृत महोत्सव



GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. To F.6/DFS/MS/GH/2023/SZ/ 550

Dated: 31./10./2023

The Addl. Commissioner of Police, Lic/Branch, 1st Floor, P.S Defence Colony New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s "Arien International" at E-189, Kalkaji, New Delhi-19

Sir,

This has reference with MHA Portal ID 2023100616853 dated 16-10-2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department in the presence of Mr. D S Rawat (Manager) on 25.10.2023. The shortcomings observed are as below:

- 1. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016
- 2. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
- 3. Temperary Kitchen at Terrace not acceptable as per clause 7.31 in UBBL 2016.

Further, the occupancy of guest house is at GF, FF & second floor of the building comprised of Basement, ground plus three upper floors with over all height is 13.00 mtr as per mention MHA Portal Id. Now you are hereby requested to submit height verification certificate & plans/section/elevation drawings of the building upto last occupied floor as guest house occupancy, for further action in the matter.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

DIRECTOR LHI FIRE SERVICE