

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

NO. F6/DFS/MS/SZ/2023/ 574

DATED: 67//1/2023

To,

The Principal
Central academy International school,
(Virender Ghai Educational society Regd.)
Sector – 10, Dwarka, New Delhi – 110075.

Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Central academy International school, (Virender Ghai Educational society Regd.) Sector - 10, Dwarka, New Delhi - 110075.

Sir.

Please refer to your Email dated 21/11/2023 on the subject mentioned above. In this connection it is to inform you that the inspection of the premises was carried out by the officers concerned of this department on 22-11-2023 in the presence of Mr. Akash Pandey from fire safety point of view.

During the course of inspection followings shortcoming have been observed:-

- 1. Six m wide internal road around the building found enchroached/blocked.
- 2. Fire Check Doors found not provided.
- 3. Yard Hydrants found not provided.
- 4. Smoke exhaust fans in the basement found inadequate & not interlinked with MOEFA.
- 5. Manually operated fire alarm system (MOEFA) found nonfunctional
- 6. Public address system found nonfunctional.
- Main pump of 2280 lpm jockey pump of 180 lpm and standby pump of 2280lpm & water curtain pump of 900LPM at ground level found not provided.
- 8. Terrace level pump found nonfunctional on auto mode.
- 9. Under Ground Fire water storage tank required 2,00,000 ltrs capacity not seen at the site.
- 10. Exit signage found not provided.
- 11. Pressurization of Lift Shaft found not provided and lift lobby must constructed in basement
- 12. PA System Panel, Battery backup & Building Floor Plans in fire control room found not provided.
- 13. Four rooms are constructed at terrace, the same has not been shown in the approved plan.
- 14. Exhaust fan must be provided in Atrium, as atrium found covered.

In view of the above shortcomings issuance of Fire Safety Certificate from fire safety point of view cannot be considered at this stage. You are directed to comply the shortcomings under intimation to this department for further consideration in the matter.

(Director)

Delhi Fire Service

Copy to:- 1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

2. The Joint Director (Building) DDA, Vikas Sadan, INA, Delhi-110023