

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/GH/2023/ 598
To,

Dated: 18-12-2023

Mr. Nisha Devi,
House No.C-159,
Prashant Vihar, Rohini,
Delhi-110085.

Sub: Issue of FSC in r/o M/s Church House Guest House at Plot no. 2, Pocket 8A, Sector-15 Rohini, Delhi-89.

Sir,

This is in reference to your online application No. 2023110117991 dated 13.11.2023 received through outdoor diary no. 2061 dated 01.06.2022 on the subject cited above. The premise was inspected by the concern nominated authority of this department on **30.11.2023**, in presence of **Mr. Prateek** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. CO detector system not provided in compliance of notification dated 27.05.2016.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doi_t_fire/FIRE/Home/Fire+Safety+Acts+and+Rule
s/http://www.delhi.gov.in/wps/wcm/connect/doi_t_fire/FIRE/Home/Forms

Yours faithfully

(Atul Garg)

DIRECTOR

Ph; 011-23414000

Copy to:-

MHA Portal Id No. 2023110117991 dated 13.11.2023