



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/Business/SZ/2023/ 4430

Dated: 13 / 12 /2023

To

Sh. S B Raimedhi, IPS, Superintendent of Police (Project), NIA Headquarters, New Delhi-110003

Sub: Renewal of Fire Safety Certificate in r/o NIA Headquarters, Office Building at Opposite CGO Complex, Lodhi Road, New Delhi.

Sir,

Please refer to your letter No. Project-E-48/001-HQ-Offi/2013/NIA/16244 dated 09/11/2023 received through this department outdoor diary No. 8561 dated 13/11/2023, on the subject cited above. In this connection, the NIA Headquarters building was inspected by the officer concerned of this department on 05/12/2023 to adjudge the availability and operability of fire safety measures provided therein. During the course of inspection Sh. Alok Pandey (Sub Insp.) & Sh Dev Kumar (Fire Operator) was present. The shortcomings observed are as below.

- 1. The ventilation/smoke management system in basement found non-functional.
- The old/waste material/furniture was piled up in basement, which is hazardous from fire safety point of view as numerous vehicles are parked in the basement.
- The hose reel hose found provided but non-functional at 1st floor and without shut-off nozzle in basement. The condition of most of the hose-reel drums was unsatisfactory.
- The automatic fire detection system found non-functional at all floors and in an office at 6th floor, even the detectors cover was not removed.
- The diesel (standby) fire pump was non-functional and other fire pumps were not on auto mode also insufficient light and poor cleanliness/maintenance observed in fire pump room.
- 6. The hydrant boxes found provided but rusted/corroded.

In view of the above, the application for renewal of Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the above mentioned shortcomings under intimation to this department for further consideration in the matter.

Yours faithfull

(ATCL GARG) DIRECTOR

DELHI FÍRE SERVICE

OR 182