



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2023/WZ/ 603

Dated: 22-12-2023

To,

The Principal,
Adarsh Shiksha Sansthan,
B-2, Block, Ashok Vihar, Ph-II,
Delhi-110052.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Adarsh Shiksha Sansthan, B-2, Block, Ashok Vihar, Ph-II, Delhi-110052.

Sir,

This has reference to your letter number A.S.S./32/23-24/05 dated 01/12/2023 received via outdoor diary number 10345 dated 04/12/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 08.12.2023 to see the compliance of the requisite fire safety measures. Smt. Parul Gupta (Administrator) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of Basement, Ground plus First floor. Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. The width of staircases for upper floors is 1.40 m & 1.17 m against the required width of 1.50 m each.
2. The width of staircases for basement is 1.10 m, 1.20 m & 1.05 m against the requirement of two staircases of 1.50 m width each.
3. Fire check doors not provided in basement.
4. Width of corridor found obstructed by metal gates which has to be removed.
5. Smoke ventilation system not provided in basement.
6. Exit signage's found not provided.
7. Form I not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Atul Gang)
Director

Ph. 011-23414000

ou R

13/12

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.