



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



DFMS-4

C-31

No.F6/DFS/MS/School/SZ/2024/42

Dated: 08/02/2024

To

The Principal,
M/s R.R. Modern School,
Kh.334, Gali no. 8/B, Sindhu Farm Road,
Meethapur Extn., Badarpur, New Delhi-44.

Sub: Regarding renewal of Fire Safety Certificate in respect of M/s R.R. Modern School located at Kh.334, Gali no. 8/B, Sindhu Farm Road, Meethapur Extn., Badarpur, New Delhi-44.

Sir,

This has reference to your letter no. RRMS/01/2023-24 dated 18.12.2023 on the subject cited above. In this context it is informed that the said building was inspected by the officer concerned of this department on 06.02.2024 in the presence of Mr. Jogender Sharma (Owner) and it was observed that school building is comprised of Ground + 02 upper floors. During the inspection following shortcoming were observed:-

1. Hose reel drum is damage at 1st & 2nd floor must be replaced.
2. Fire pump having capacity 220 LPM provided against the requirement of 450 LPM.
3. Overhead tank capacity 3,000 liters provided against the requirement of 10,000 liters.
4. Exit sinages found removed.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.