

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2024/SZ/46  
To

Dated: 09.02.2024

The Addl. Commissioner of Police,  
Lic/Branch, 1<sup>st</sup> Floor, P.S Defence Colony  
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Hotel Atithi located at F-5, East of Kailash  
New Delhi-110065

Sir,

This has reference with **MHA Portal ID 2023112018694 dated 25-01-2024** on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 06/02/2024 in the presence of Md. Sabbir. During the inspection, it was observed that the Guest House is running 2<sup>nd</sup> & 3<sup>rd</sup> floor in the building comprised of Basement ground plus three upper floors. The shortcomings observed are as below:

1. Fire check doors not provided as per clause 7.31 of UBBL 2016.
2. Smoke management system not provided in the upper floor as per clause 7.31 of UBBL 2016.
3. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
4. Terrace level tank capacity 2000 ltrs provided against the required capacity of 5,000 ltrs.
5. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE