

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2024/SZ/ 58
To

Dated: 15/02/2024

The Addl. Commissioner of Police,
Lic/Unit, 1st Floor, P.S Defence Colony
New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Mayur located at A-68, Chittranjan Park,
New Delhi 110019

Sir,

This is in reference with **MHA Portal ID 2024012000651 dated 26/01/2024** on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 09.02.2024 in the presence of Mr. S. T Khan (GM) of the Guest House. During the inspection, it was observed that the Guest House is running Ground + Two Upper Floors. The shortcomings observed are as below:

1. There is one staircase having width of 1.0 mtr. The minimum widths of two staircases are required 1.50 mtr each as per UBBL-2016.
2. Smoke management system not provided as per clause 7.31 of UBBL 2016.
3. First Aid Hose Reel provided but not in working.
4. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
5. The MOEFA system is not provided.
6. Terrace level Fire Pump not on auto mode.
7. Overhead tank capacity 2000 ltrs provided against the required capacity of 20,000 ltrs.
8. The Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

dgn