

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/DFS/MS/Business/NDZ/2024/ 211

Dated: 22/04/2024

To,

The Commissioner,  
Municipal Corporation of Delhi,  
Dr. SPM, Civic Centre, New Delhi - 02.

**Sub:** Regarding renewal of Fire Safety Certificate in respect of **Akarshan Bhawan** located at **4754-57/23, Ansari Road, Darya Ganj, Delhi.**

Sir,

This has reference on the subject cited above. In this connection, it is to inform you that the building/ premises was inspected by the officer concerned of this department on dated 09.04.2024 in the presence of Mr. Atul (T9 Office). During inspection, the shortcomings communicated vide letter no. F6/DFS/MS/Business/NDZ/2023/854 dated 30.08.2023 still exists:

1. First aid hose reel found non functional.
2. Alternate power source for control panel not provided.
3. MOEFA not provided.
4. Public address system found not functional.
5. Automatic sprinkler system in basement found not functional due to non availability of water in overhead water tank.
6. Exit signages are not adequately provided.
7. Fire pump not in auto start mode.
8. Overhead water storage tank provided is 30,000 ltrs. against the requirement of 50,000 ltrs and even the tank was found empty.
9. Lift signages are not provided.
10. Standby power supply not provided.

In view of above shortcomings, the occupancy of the building /premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

The owner/ occupier is requested to rectify the shortcomings at the earliest for further action.

Yours faithfully,

  
(Atul Garg)  
Director  
Delhi Fire Service  
Tel:-011-23414000  
o/c  
22/4

**Copy to:-**

Mr. Sohan Singh Slathia (Secretary),  
Akarshan Bhawan, Flat Owners Welfare Association,  
4754-57/23, Ansari Road, Darya Ganj, Delhi - 02.