

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No.F.6/DFS/MS/2024/369

Dated: 01/07/2024

To,

Sh. Inderjit Singh (President),
Barakhamba Tower Apartment owners Association,
Barakhamba Tower, 22 Barakhamba Road,
New Delhi.

Sub:- Renewal of fire safety Certificate for Barakhamba Tower (previously known as Skipper Bhawan) at 22, Barakhamba Road, New Delhi.

Sir,

This has reference to letter no. nil dated 27/05/24 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 19/06/24 in the presence of Sh. Inderjeet Singh and the following shortcomings were observed:-

1. Detectors found non functional.
2. Pressurization of staircases found nonfunctional.
3. MOEFA found non functional.
4. Diesel engine pump found non functional.

In view of above shortcomings, request for renewal of fire NOC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully



(Atul Gang)
DIRECTOR

Delhi Fire Service

Copy to:-

1. The Chief Architect, New Delhi Municipal Council, Palika Kendra, New Delhi.