

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2024/ 270

Dated:- 28/06/2029

Yours faithfully

Director

To.

The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony,

Sub.:- Regarding issuance of Fire Safety Certificate in respect of M/s. Echoes (A Unit of Hadhpalatable Foods Private Limited), located at Property No. 3, J-Block, Reserve Bank Enclave, Paschim Vihar, Delhi-110063

This has reference to online application no. 2024060308687 dated 12/06/2024 on the subject cited above. In this connection it is to inform you that the above said restaurant building have been inspected by the officer concerned of this department from fire safety point of view on 21/06/2024 in the presence of Sh. Harshit Mehta (Owner). During inspection, it has been observed that the said restaurant is running on first floor and the building is comprised of Basement + Stilt + Upper Ground Floor + 03 Upper Floors served with 03 staircases. However, the following shortcomings have been observed as under:-

- Alternate staircase shall be extended up to terrace.
- 2. Fire Check Door is not provided.
- 3. A fire Pump of 450 lpm capacity on the terrace is not provided.
- 4. An over head water storage tank of 20,000 ltrs. capacity is not provided.
- 5. Down Comer & First Aid Hose Reel Hose are not provided.
- 6. Exit signages are not provided.

In view of the above shortcoming, the application for issuance Fire Safety Certificate cannot be considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/statutory Authority may take suitable necessary action as deemed fit.

Copy to:-

 Sh. Harshit Mehta, M/s. Echoes (A Unit of Hadhpalatable Foods Private Limited), located at Property No. 3, J-Block, Reserve Bank Enclave, Paschim Vihar, Delhi-110063.