

2/60

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2024/SZ/ 393
To

Dated: 04/07/2024

The Joint Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony,
New Delhi 110049

Sub: Regarding issuance of FSC in r/o M/s The Legend Inn situated at E-4, East of Kailash, New Delhi 110065

Sir,

This has reference with **MHA Portal 2024050206677 dated 06.07.2024** on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 01/07/2024 in the presence of Mr. Vineet Kumar. During the inspection, it was observed that the building comprised of Basement + Ground + 03 upper floors. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Fire check door not provided as per clause 7.31 of UBBL 2016.
2. Smoke ventilation system provided but found non-functional.
3. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

