

531

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/ 2024/ 457

Dated:- 19/07/2024

To,
The Head Of School,
Asian Public School,
Ranjit Singh Marg, Meer Dard Road,
New Delhi.

Sub: Regarding issuance of FSC in r/o Asian Public School located at Ranjit Singh Marg, Meer Dard Road, New Delhi.

Sir,

This has reference to mail id asianpublicschooln@gmail.com dated 24/06/2024, on the subject cited above. In this regard, it is to inform you that the site was visited by officer concerned of this department on 08.07.24 in the presence of Sh Mirja Mehtab Begh and following shortcomings were observed.

1. Width of staircases is required of 1.5 m each against the provision of 1.0 meter each.
2. Width of exit door of class room at first floor is required of 1.2m against the provision of 1.0 Meter.
3. Hose reel not provided.
4. Overhead tank of 10,000 liter capacity & fire pump of 450 LPM are not provided.
5. Exit Signage shall be provided in school building.

In view of above, fire safety certificate (FSC) cannot be considered at this stage. Therefore, it is requested to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully,


(Atul Gang)
DIRECTOR
Delhi Fire Service

Copy to:-

1. The Director (Education), Govt. of NCT, Old Sectt. Delhi - 54.