



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/8
आजादी का
अमृत महोत्सव

No.F6/DFS/MS/Industrial/SZ/2024/ 436

Dated: 05/08/2024

To

The Authorized Signatory,
M/s Interocean Shipping (India) Private Limited,
Plot No. A-17, M.C.I.E. Mathura Road,
New Delhi-44.

Sub: Regarding renewal of Fire Safety Certificate in r/o **M/s Interocean Shipping (India) Private Limited**, located at **Plot No. A-17, M.C.I.E. Mathura Road, New Delhi-44.**

Sir,

This has reference to the letter bearing outdoor diary no. 3979 dated 09.07.2024 on the subject cited above. In this context, it is to inform you that inspection of said premises/building was carried out by a team of officers concerned of Delhi Fire Service on 29.07.2024 in the presence of Mr. Suresh Kumar Dahiya (Admin.) and it was observed that building is comprised of 2 tier Basements + Ground + 02 upper floors. During the inspection following shortcoming were observed:-

1. Vertical & Horizontal Openings found not sealed.
2. Hose reels & internal hydrant and sprinkler system found non functional.
3. No hose & branches were found in Hose boxes.
4. No hydrant outlet was found on terrace.
5. Sprinkler heads to be extended below the ventilation ducts in basement and below false sealing at upper floors.
6. Pressurization system of lift well & lift lobby found non functional.
7. Terrace fire pump found non functional.
8. The length of Hose reel at ground floor must be extended.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)
Director

Delhi Fire Service

Copy to:-

- 1 The Executive Engineer (Building), MCD, Jal Vihar, Lajpat Nagar, New Delhi-24.