

C-28

DFA
FT

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/SZ/2024/ 497

Dated: 07/08/2024

To,

The Principal,
ITBP Sr. Sec. School,
Sector 16 B, Dwarka,
New Delhi. (Hostel block)

Subject: Issuance of Fire Safety Certificate in r/o ITBP Sr. Sec. School (Hostel block) Located at Sector 16 B, Dwarka New Delhi.

Sir,

Please refer to Letter No- ITBP/Misc.corress/2024-25/142 dated 28/06/2024 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officers concerned from this department on 26/07/2024 in presence of Sh. Surjan Singh (Principal) for fire safety point of view.

During the course of inspection following shortcomings are observed.

1. Fire Check Doors closer of FCD/FCD found damaged at same places.
2. Hose Reels & Hydrants system found nonfunctional.
3. Sprinkler system in basement found nonfunctional
4. All the Pumps at ground & terrace level found nonfunctional.
5. Smoke management systems found provided but nonfunctional.
6. The pressurization of lift shaft & lift well found not provided/ nonfunctional.
7. Exit signage's found removed at some places.
8. Dimension/ capacity of underground & over head fire water tank not submitted.

You are requested to comply the abovementioned shortcomings under intimation to this department.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

(Atul Gargy)
Director

Delhi Fire Service

Copy to:-

1. Directorate of Education Old Secretariat Delhi – 110054

g/c
31/8/24