

d/sr

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/GH/SZ/2024/ 457

Dated: 02/08/2024

To

The Joint Commissioner of Police,  
Licensing Unit 1st Floor,  
P.S Defence Colony,  
New Delhi-110049.

**Sub:- Regarding renewal of Fire Safety Certificate in respect of M/s Hotel Kochar Continental,  
Located at 59/28, New Rohtak Road, Karol Bagh, New Delhi-110005.**

Sir,

Please refer to your Online Application No. 2023030703299, dated 09/07/2024, on the subject cited above. In this connection, it is to say that the aforesaid guest house has been inspected by the officer concerned of this department on 27.07.2024 in the presence of Ms. Chandershekhkar Manager, to check the functional ability of fire safety arrangements already provided in the guest house building & Implementation of the notification No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 in respect of existing guest house building . During the inspection the following shortcomings were observed;-

3. Fire Check Doors are not provided.
4. Smoke exhaust system found not functional/ inadequate.

In view of the above, as per the notification No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019, the FSC issued vide letter No F6/DFS/MS/GH/SZ/2022/30, dated 17/01/22, is immediately suspended. In the absence of fire safety certificate this guest house is not safe from fire safety point of view. You are advised to rectify the above mentioned shortcomings and apply a fresh on MHA portal for further necessary action in this matter.

Copy to :-

1. The Manager, M/s Hotel Kochar Continental, Located at 59/28, New Rohtak Road, Karol Bagh, New Delhi-110005.

  
(Atul Garg)  
Director  
Delhi Fire Service  
07c  
29/07/24