GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/WZ/School/2024/ 524

Dated: 16 08 /2024

To,

The principal, Queen's Convent School, Sec-25, Rohini, Delhi-110085.

Sub: Issue of FSC in r/o Queen's Convent School, Sec-25, Rohini, Delhi-85.

Sir,

Kindly reference to online e-mail dated 24.06.2024, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 31.07.2024 in presence of Sh. Brij (Caretaker) to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Terrace Fire pump with capacity 450 LPM provided but not functional.

2. Ground level jockey Fire pumps with capacity of 225 LPM provided but not functional.

3. Terrace tank found empty.

One more block ground + 01 upper floor found occupied in same premises.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under: http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully