

c77

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 581

Dated: 12/09/2024

To,

The Manager,
M/S Sindh Palace" Guest House,
7966, Arakashan Road, Pahar Ganj,
New Delhi.

Sub: Regarding renewal of FSC in r/o M/S Sindh Palace" Guest House, 7966, Arakashan Road, Pahar Ganj, New Delhi.

Sir,

This has reference to your online ID No. 2024081412690 dated 14-08-2024, on the subject cited above. In this regard, it is to inform you that the site was visited by the officer concerned of this department on dated 04/09/24 in presence of Mr. Ashish and following shortcomings were observed:

1. CO detectors found non functional.
2. PA system found non functional.
3. MOEEFA found non functional.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter

Yours faithfully,


(Atul Garg)
DIRECTOR
Delhi Fire Service
✓ 6/2
9/9

Copy to :-

1. The Addl. Commissioner of Police (Lic.) First floor, PS Defense Colony, New Delhi.