

c/126

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No. F6/DFS/MS/2024/NDZ/GH/596

Dated: 20/09/2024

To

The Manager,  
M/S Mayur Guest House,  
51, Arakashan Road,  
Pahar Ganj New Delhi.

**Sub:-** Issuance of FSC (Fire Safety Certificate) in r/o M/S Mayur Guest House, 51, Arakashan Road, Pahar Ganj New Delhi.

Sir,

This has reference to on line ID No. 2024082413083 dated 24/08/24, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 06/09/24 in the presence of **Manager** and following shortcomings were observed: -

1. Hose reel found nonfunctional.
2. Hydrant found nonfunctional.
3. Pump not in auto mode provisions.
4. Earlier, reception and lobby was allowed at ground /upper ground floor where as restaurant is running at ground /upper ground floor, same is not allowed.
5. Building plan of all floors is also not up loaded online portal.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

  
(Atul Garg)  
DIRECTOR  
Delhi Fire Service

**Copy to:-**

1. The Addl. Commissioner of Police (Lic.) First floor, P.S. Defense Colony, New Delhi.