

c/98

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 2024/ 650

Dated: 22/10/2024

To,
The Manager,
Delhi Continental Guest House, 8218-19,
Arakashan Road, Pahar Ganj,
New Delhi.

**Sub: Regarding renewal of FSC in r/o M/S Delhi Continental Guest House, 8218-19,
Arakashan Road, Pahar Ganj, New Delhi.**

Sir,

This has reference to your online id no. 2024100515289 dated 05/10/2024, on the subject cited above. In this regard, it is to inform you that the site was visited by the officer concerned of this department on dated 14/10/24 in presence of Sh. Amit Pal, **Manager** and following shortcomings were observed:

1. Smoke management system found non functional.
2. CO detectors found non functional.
3. PA system found non functional
4. Pump found non functional.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter

Yours faithfully,

(Amit Garg)
DIRECTOR
Delhi Fire Service

Copy to :-

1. The Addl. Commissioner of Police (Lic.) First floor, PS Defense Colony, New Delhi.