

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 459
 To

Dated: 16/10/2024

The Joint Commissioner of Police,
 Lic/Branch, 1st floor PS Defence colony,
 New Delhi -110049

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s F ONE CAFÉ (A unit of Shivam Hospitality) at F-1. Second Floor, Kalkaji, New Delhi 110019

Sir,

This has reference with **MHA Portal ID 2024091914426** dated **19/09/2024** on the subject cited above. In this concerned, it is to inform you that the premise was inspected by the concern nominated authority of this department on 14/10/2024 in presence of Mr. Lala Ram Verma to verify the fire safety measures installed in the building and observed that the building is comprised of Basement, Ground + Three upper floor but restaurant running at Second & Third Floor only. Accordingly fire safety arrangement were tested / checked and found following observation.

1. The width of rear side iron staircase is between 1.40 to 1.50 mtr from first floor to third floor and the width of mid landing is less than of 1.50 mtr. One tailoring/ draper shop is running beneath the front side staircase, which need to be removed.
2. Width of exit corridor leading to staircase at third floor is between 1.20 mtr to 1.40 mtr wide against the required width of 1.50 mtr.
3. First aid hose reel provided but found nonfunctional.
4. Automatic fire detection not provided.
5. Internal hydrant provide but found not functional
6. one Electrical Fire Pump capacity 1620 LPM, one Diesel Engine Pump 1620 LPM and one Jockey Pump 180 LPM provided against the required Electrical fire pump capacity 2280 LPM, one Diesel Engine pumps 2280 LPM.
7. Dedicated fire fighting pump 450 LPM not provided at terrace level.
8. Dedicated Overhead tank capacity 10,000 ltrs not provided.
9. Exit signage not provided.
10. U.G. Fire fighting tank was half filled. Further, draw off connection, fire service inlet and access to tank not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall not be allowed. The liability of loss of life and property in case of any eventuality/ misshape shall be at the owner/occupier side. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


 (ATUL GARG)
 DIRECTOR
 DELHI FIRE SERVICE